


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-059	Smoke	9/8/2008	ADS/TM	S11AA1002MH	Dry	Yes	725.08



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-059	Smoke	9/8/2008	ADS/TM	S11AA1002MH	Dry	Yes	725.08

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13YY_018G1	S13YY_018MH	S13YY_014MH	113.8825	8
S11AA1002G1	S11AA1002MH	S13YY_018MH	281.6462	8
S11AA1009G1	S11AA1009MH	S11AA1002MH	329.548	8

Observations & Photos

Obs_ID S1028-059-OB01

Address 3253 Yosemite Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1009MH

Comments Smoke from cleanout in front yard. 3253 Yosemite Ave



Picture \S1028-059-OB01-P01.jpg

Comments Front of house, 3253 Yosemite Ave